

EXCAVATOR- 2005 CAT

DATE	NATURE OF REPAIR	COST	REPAIR DONE IN HOUSE
6/22/20	A/C recharge bottle for A/C	\$45.99	YES
2/26/21	Repaired A/C by replacing temperature sensor in ductwork	\$901.75	NO
6/7/21	Replaced front upper windshield wiper	\$93.26	YES
6/9/21	Repaired tire	\$50.50	NO
6/9/21	Repaired tire	\$50.50	NO
2/4/22	Rebuilt bucket	\$4,593.75	NO
2/1/22	Replaced a tire ring spacer	\$193.67	YES
2/1/22	8 Tires	\$3,716.00	NO
3/2/22	Tire installation	\$913.56	NO
3/7/22	New cutting edge for ditching bucket	\$470.08	YES
2/7/22	Repaired the climate control and the leaking fuel pump	\$1,385.71	NO
5/30/23	Hydraulic hose	\$199.26	YES
8/18/23	Swivel repair	\$8,869.86	NO
2/6/24	Steel for repairing bucket	\$66.70	YES
2/8/24	Right and left window latches	\$220.00	YES
	REPAIR TOTALS	\$21,770.59	